

Reagents, Catalyst, Oxidation and Supplies

| Elementar# | Alpha# | Description | UOM |
|--------------------------|--------------|---|-------|
| | AEB1093 | Alumina (Aluminum Oxide) Spheres (3-6mm) | 250g |
| 200010245/ 05 008 467 | AR01008 | Corundum Balls | 40g |
| 200014271/ 05 000 699 | AR189 | Copper Sticks | 100g |
| | AEB1206 | Copper Oxide Wires, Fine Wires (4 x 0.5mm) | 1kg |
| 200009554/ 05 001 039 | AR01039 | Copper Oxide Wires, Fine Wires | 250g |
| | AEB1209 | Copper Oxide Wires, Fine Wires (4 x 0.5mm) | 3kg |
| | AEB1083M | Copper Wires Pound Pack, Fine Wires Reduced (4 X 0.5mm) | 454g |
| | AEB1255 | Quartz Wool Discs (24mm) | 25 |
| | AEB1216 | Silica (Quartz) Chips Granular (2-4mm) | 100g |
| 200004827/ 03 679 908 | AR177 | Quartz Wool, Fine (9 Micron) | 50g |
| | AEB1276 | Silica (Quartz) Wool, Very Fine | 15g |
| 200005872/ 22 131 365 | AR22365 | Silver Wool, Fine Wire (.05mm) | 50g |
| 200008986/ 11.02-0008 | AEB1299 | Tungsten (VI) Oxide Granular | 300g |
| 200008986/ 11.02-0008 | AR2181 | Tungsten Trioxide | 60g |
| 200012531/ 11.02-0024 | AR20024 | Tungsten Oxide Powder | 90g |
| 200009890/ 11.02-0017 | AR20017 | Tungsten Oxide Fine Powder | 25g |
| 200010974/ 12.00-0040 | AR02530 | Tungsten Metal For Use On Elementar Analyzers | 500g |
| 200009890/ 11.02-0017 | AR02530-2500 | Tungsten Metal, Bulk, For Use On Elementar Analyzers | 2.5kg |
| 200010174/ 12.01-0045 | AR02530X | Tungsten Kit Complete With 500G (AR02530) Of Tungsten | |

Crucibles and Boats

| Elementar# | Alpha# | Description | UOM |
|--------------------------|---------|-------------------|-----|
| 200006654/ 25.00-1123 | AEC3058 | Ceramic Crucibles | 100 |
| 00014515/ 03 002 278 | AR2278 | Metal Crucibles | 100 |



Corundum Balls
AR01008
(200010245/50 008 467)



Copper Sticks
AR189
(200014796/38.00-1290)



Copper Oxide Wires, Fine Wires
AR01039
(200009554/05 001 039)



Tungsten Trioxide
AR2181
(200008986/11.02-0008)



Tungsten Oxide Fine Powder
AR2181
(200009890/11.02-0017)



Tungsten Metal For Use On Elementar Analyzers
AR02530
(200010974/12.00-0040)

Operation Accessories


| Elementar# | Alpha | Description | UOM |
|----------------------------|------------|--|------|
| 200015256/ 03 002 399 | AEE1174 | Filter (18mm) | EA |
| 200015256/ 03 002 399 | AEE1174-10 | Filter (18mm) | 10 |
| 200008236/ 05 000 049 | AEE2517 | GI14 Screw Cap | EA |
| 200006785/ 05 000 094 | AEE2505 | Gloves, Temperature Resistant | Pair |
| 200009657/ 11.00-0500/4 | AEE2521 | Manually Operated Drill for Cleaning Tubes | EA |
| | AR2213 | Leak Detection Solution | 8oz |
| 200006998/ 03 968 006 | AR241 | Silicone Grease | 150g |

Supplies for Furnace Tubes


| Elementar# | Alpha# | Description | UOM |
|----------------------------|------------------|--|-----|
| 200009235/ 25.20-1003 | AR01003 | Connecting Tube Transparent Silica (130mm) | EA |
| 200004147/ 11.00-1331/4 | AR13314 | Connecting Tube Trasparent Silica, Includes O-rings | EA |
| 200011961/ 12.01-1032/4 | AR11032/4 | Distance Ring | EA |
| 200009548/ 25.20-0004 | AEE2522 | Gripper Arm With O-rings For vario MAX In CNS Mode | EA |
| 200010457/ 12.01-1008/4 | AR02530S | Tungsten Spacers For Elementar, for use with AR02530 | 25 |
| | AR02530S -100 | Tungsten Spacers For Elementar, for use with AR02530 | 100 |
| 200006395/ 50 008 449/4 | AR08449/4 | Wire Screen (26.8mm) | EA |



**Connecting Tube
Trasparent Silica
Includes O-rings**
AR13314
(200004147/11.00-1331/4)



**Tungsten Spacers for
Elementar, for use with
AR02530**
AR02530S
(200010457/12.01-1008/4)



**Combustion Tube,
Quartz, vario MAX**
AR01028
(200005357/25.00-1028)



**Combustion Tube
Stainless Steel, vario
MAX**
AR01030
(200014722/25.00-1030)

Quartz, Glassware, and Furnace Tubes

| Elementar# | Alpha# | Description | UOM |
|----------------------------|---------|--|-----|
| 200005357/ 25.00-1028 | AR01028 | Combustion Tube, Quartz, vario MAX | EA |
| 200014722/ 25.00-1030 | AR01030 | Combustion Tube Stainless Steel, vario MAX | EA |
| 200007844/ 11.00-1150/4 | AR11504 | Combustion/Reduction Tube | EA |
| 200013540/ 22 160 200/4 | AEC3008 | Drying Tube | EA |
| 200013540/ 22 160 204/4 | AEC3066 | Drying Tube, Straight | Ea |
| 200013679/ 25.00-1048 | AR01048 | Post Combustion Tube | EA |
| 200008838/ 25.00-0017 | AR01007 | Quartz Combustion Tube, For Elementar | EA |
| 200013606/ 34.00-1339/4 | AEC3038 | U-Tube Large Complete with GL18 Caps | EA |

O-ring

| Elementar# | Alpha# | Description | UOM |
|--------------------------|------------|---------------------------|-----|
| 200010589/ 03 002 395 | AR02395 | O-ring for Gripper Arm | EA |
| 05 000 248 | AR00248 | O-ring Silicone Rubber | EA |
| 03 654 701 | AR54701 | O-ring Silicone (4 x 4mm) | EA |
| 200015397/ 05 000 369 | AR00369 | O-ring (4 x 4mm) | EA |
| 200007224/ 03 654 627 | AR54627 | O-ring (20 x 2mm) | EA |
| 200007224/ 03 654 627 | AR54627-10 | O-ring (20 x 2mm) | 10 |

O-ring

| Elementar# | Alpha | Description | UOM |
|--------------------------|----------------|-----------------------------|-----|
| 200007217/ 05 000 095 | AR00095 | O-ring (22 x 2mm) | EA |
| 200007217/ 05 000 095 | AR00095- 10 | O-ring (22 x 2mm) | 10 |
| 200006004/ 05 000 416 | AR00416 | O-ring (7.5 x 2.mm) | EA |
| 200006004/ 05 000 416 | AR00416- 10 | O-ring (7.5 x 2.mm) | 10 |
| 200008183/ 05 000 359 | AR00359 | O-ring (9.19 x 2.62mm) | EA |
| 200008183/ 05 000 359 | AR00359- 10 | O-ring (9.19 x 2.62mm) | 10 |
| 200008068/ 03 002 268 | AR02268 | O-ring (32 x 3mm) | EA |
| 200006094/ 05 000 425 | AR00425 | O-ring (5 x 1.5mm) | EA |
| 200009565/ 03 002 850 | AEE1176 | O-ring (4 x 2mm) | EA |
| 200005999/ 05 000 353 | AR50353 | Quadring (7.65 x 1.78mm) | EA |
| 200005999/ 05 000 353 | AR50353- 10 | Quadring (7.65 x 1.78mm) | 10 |
| 200006143/ 03 002 607 | AR02607 | Shaft Seal | EA |